How to install C-Bridge I driver

C-Bridge I driver installation manual

1. Introduction

C-Bridge I is a USB to Extended-UART converter.
You need to install C-Bridge I driver to your PC.

Figure 1.1 The connection between the power supply and the PC

How to install C-Bridge I driver

2. Installing the driver on Windows 10

2.1 Download the driver from our website
https://en.cosel.co.jp/form/form.php?form_id=108

Unzip the downloaded file to any location.

UARTDriver
.zip

Unzip

UART
Driver

2.2 Connect C-Bridge to your PC

2.3 Right-click start menu and click "Device Manager"

Programs and Features

Mobility Center

Power Options

Event Viewer

System

Click

Device Manager

Network Connections

Disk Management

Computer Management

Command Prompt

Command Prompt (Admin)

Task Manager

Control Panel

File Explorer

Search

Run

Shut down or sign out

Desktop

Search Windows

Right-click

How to install C-Bridge I driver

2.4 Right-click on "USB Serial Device (COMx)" in "Ports (COM & LPT)" and click "Update Driver Software..."


2.5 Click "Browse my computer for driver software"

How to install C-Bridge I driver

2.6 Select the folder where you unzipped the downloaded file.

2.7 Wait for the driver to be installed.
　　Click the "Close" button.

How to install C-Bridge I driver

2.8 When installation is properly completed, "USB CDC device (COMx)" is shown in "Ports (COM & LPT)".